SoCalGas-6

Prepared Reply Testimony of Robert A. Carnahan, P.E. (March 20, 2020)

I.19-06-016

ALJs: Hecht/Poirier

Date Served: March 12, 2021

Order Instituting Investigation on the Commission's Own Motion into the Operations and Practices of Southern California Gas Company with Respect to the Aliso Canyon storage facility and the release of natural gas, and Order to Show Cause Why Southern California Gas Company Should Not Be Sanctioned for Allowing the Uncontrolled Release of Natural Gas from Its Aliso Canyon Storage Facility. (U904G).

I.19-06-016 (Filed June 27, 2019)

CHAPTER II

PREPARED REPLY TESTIMONY OF ROBERT A. CARNAHAN, P.E. ON BEHALF OF SOUTHERN CALIFORNIA GAS COMPANY (U 904 G)

March 20, 2020

1	
2	TABLE OF CONTENTS
3	I. VERTILOG TECHNOLOGY CIRCA 1988 HAD LIMITED ACCURACY AND WAS NOT A RELIABLE OR DETERMINATIVE INDICATOR OF CASING INTEGRITY, 1
4 5 6 7	 A. Background Regarding Vertilog Technology. B. The Circa 1988 Vertilog Technology Had Limitations. C. Due to Limitations with Vertilog, Superior Tools Such As High Resolution Vertilog (HRVRT) and Ultrasonic Imager Tool (USIT) Were Developed. D. Follow-up Analyses by More Accurate Methods—USIT and HRVRT— Confirmed that the Circa 1988 Vertilogs Returned False Positives and Were
8	Therefore Not Reliable
9	A RELIABLE INDICATOR OF CORROSION ISSUES ON SS-25
10	III. CONTRARY TO PAO'S ASSERTION, PRESSURE TESTS ARE PRIMARILY USED TO IDENTIY EXISTING LEAKS AND CRITICALLY SIZED DAMAGE." 19
11 12	IV. PAO AND SED BOTH INCORRECTLY ASSUME THAT CATHODIC PROTECTION (CP) WOULD HAVE PREVENTED THE LEAK
13	V. SED IS INCORRECT THAT CONTINUOUS PRESSURE MONITORING AND TEMPERATURE/NOISE SURVEYS SHOULD HAVE ALERTED SOCALGAS TO
14	THE SS-25 LEAK PRIOR TO OCTOBER 23, 2015
15 16	A. Continuous Pressure Monitoring would Not Have Anowed Socardas to Detect the Leak Before It Occurred
17	VI. CONCLUSION
18	WITNESS QUALIFICATIONS
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
	i
	1

1	CHAPTER II
2	The purpose of my prepared reply testimony on behalf of Southern California Gas
5	Company (SoCalGas) is to respond to the testimony of Margaret Felts on behalf of the Safety and
5	Enforcement Division (SED) ¹ and Mina Botros, Alan Bach, Matthew Taul, Pui-Wa Li, and Tyler
5	Holzschuh on behalf of the Public Advocates Office (PAO) of the California Public Utilities
7	Commission (CPUC). Specifically, SED alleges violations of Section 451 of the California
8	Public Utilities Code because SoCalGas should have used the Vertilog technology to check the
9	casing on 13 wells (Violations 61-73), ² should have used cathodic protection to prevent the
10	corrosion that led to the SS-25 leak (Violation 86), and because not having a continuous pressure
11	monitoring system for well surveillance prevented the immediate identification of the SS-25 leak
12	and accurate estimation of gas flow rate (Violation 87). ³ Public Advocates Office (PAO) alleges
13	further that corrosion on the SS-25 well would have been timely identified if SoCalGas had
14	assessed those 13 wells, including SS-25, ⁴ and that cathodic protection could have mitigated
15	corrosion on SS-25.5 These arguments ignore that the Vertilog technology was not reliable, that
16	PAO's simple corrosion rate calculation is unreliable and speculative, that pressure tests are not
17	intended to detect corrosion, that cathodic protection would not have protected the production
18	casing on SS-25, and that continuous pressure monitoring could not have prevented "catastrophic
19	failure" of SS-25. Moreover, Ms. Felts' contention that the leak existed prior to October 23, 2015
20	is unsupported.
21	I. VERTILOG TECHNOLOGY CIRCA 1988 HAD LIMITED ACCURACY AND
22	WAS NOT A RELIABLE OR DETERMINATIVE INDICATOR OF CASING INTEGRITY.
23	PAO alleges that "SoCalGas management failed to deal with integrity management issues
24	
25	¹ SED's Opening Testimony was served on parties to I.19-06-016 on November 22, 2019 without an
26	identified witness, and remains so. Pursuant to SoCalGas Data Request 2 to SED, SED identified Margaret Felts as the sponsoring witness for the entirety of SED's Opening Testimony.
27	 ² SED Opening Testimony at 10-12. ³ SED Opening Testimony at 47-50.
28	 ⁴ PAO Opening Testimony at 3-10. ⁵ PAO Opening Testimony at 13.

by taking prudent action in response to" Vertilog testing conducted at Aliso Canyon circa 1988.⁶
 PAO states further that, following the Vertilog inspection results, "SoCalGas' management failed
 to undertake a timely inspection" of other wells, including SS-25, and "consequently failed to
 identify and address corrosion issues."⁷

These allegations presuppose that the Vertilog technology at that time was reliable and
accurate. That is not the case.

7

A. <u>Background Regarding Vertilog Technology.</u>

Vertilog was introduced in the 1970s as a mechanism that attempts to utilize Magnetic 8 9 Flux Leakage (MFL) to detect casing metal loss.⁸ MFL tools measure magnetic leakage fields. 10 The measured field strength and field extension depend on depth and extension of metal loss, 11 metal loss feature shape, wall thickness, magnetization magnetic properties, and logging speed. 12 Historically, however, the results of the first generation of MFL tools were not very satisfactory.⁹ 13 Vertilog works by using a direct current (DC) electric coil to induce a magnetic field that 14 saturates the casing. Where the casing body has no discontinuities, the magnetic field is uniform. 15 Where discontinuities exist, the magnetic field is disturbed and magnetic flux leaks out of the 16 casing wall.¹⁰ The magnitude of magnetic flux leakage is proportional to the amount of metal 17 loss in the casing. Sensors on the Vertilog tool are intended to detect the level of magnetic flux 18 leakage, which is displayed as a voltage signal on the Vertilog chart recording.

Figure 1 below is an example of a standard strip chart used to display Vertilog raw data.
It is similar in format to the strip charts associated with the circa 1988 Vertilog-inspected wells.¹¹
Flux leakage average response is shown on the left-hand track and can be used to evaluate the
circumferential extent of a discontinuity.¹² A casing collar will produce an average signal equal

- 23
- 24 ⁶ PAO Opening Testimony at 1.
 - ⁷ PAO Prepared Testimony at 5.

^{25 &}lt;sup>8</sup> Ex. II-1 (Haire, J.N. and Heflin, J.D, Dresser Atlas, "Vertilog – A Down-Hole Casing Inspection Service," SPE 6513, 1977).

^{26 &}lt;sup>9</sup> Ex. II-2 (Goedecke, H., GE Oil & Gas"Ultrasonic or MFL Inspection, Which Technology is Better for You?," Pipeline & Gas Journal, October 2003).

^{27 &}lt;sup>10</sup> Ex. II-3 (Adams, G.W. and Moffat, W.D., Atlas Wireline Services, "Full-Signature Multiple Channel Vertilog," SPE 22101, 1991).

^{28 &}lt;sup>11</sup> Ex. II-3 (SPE 22101). ¹² Ex. II-1 (SPE 6513).

to 360 degrees in circumference. Eddy current response is displayed on the first five divisions of
the right-hand track, which is zero at the fifth division and increases to the left. The remaining 15
divisions of the right-hand track display maximum flux leakage response, which is zero at the
fifth division and increases to the right.

To *estimate* the penetration depth of a discontinuity, maximum flux leakage was read
from the strip chart, eddy current response was used to determine whether the discontinuity was
internal or external, the discontinuity was identified as an isolated pit or general corrosion, and
depth was determined from a separate calibration chart for the size, weight, and grade of casing.¹³
Wall thickness loss classifications defined in Vertilog reports are as follows: Class 1: 0-20%,
Class 2: 21-40%, Class 3: 41-60%, and Class 4: 61-80%.



substantial deficiencies.

For example, the Vertilog technology did not provide a method for differentiating isolated pitting from general corrosion. Metal loss depth cannot be accurately determined without first classifying metal loss as isolated pitting or general corrosion. The below Vertilog interpretation charts for well P-32C (Figure 2) illustrate this principle. These charts display metal loss depth class as a function of maximum flux leakage for 8 %-in 36 pound/foot K55 or N80 casing. The upper chart, used where the production casing is not enclosed within a surface casing, shows that flux leakage between 16 and 30 could be either Class 2 external general corrosion or Class 3 external isolated pitting. If metal loss were present where the casing was located within the surface casing (lower chart), flux leakage in the range 22 to 30 could be either Class 2 external general corrosion or Class 4 external isolated pitting.

1 VERTILOG INTERPRETATION CHARTS RESPONSE VS % METAL LOSS 2 CASING SIZE-8-5/8"WEIGHT- 36" GRADE-K-55 3 4 CHART-86J55E OUTSIDE 13-3/8" SURFACE PIPE 5 81%-100 41%-60% 61%-80% 21%-40% 6 CL-4PP CL-4 CL-2 CL-3 72+ 16-34 36-70 4 - 14ODIP 7 20-34 32-70 36-56 58+ TOIP 10-18 72-120 8-30 0DGC 8 70 - 112 114+ 38-68 18-36 IDGC 9 MAXIMUM FL RESPONSE IN VERTILOG UNITS 10 SURFACE PIPE 11 CASING SIZE-8-58"WEIGHT-36" GRADE- K-55 12 CHART-86J71E SURFACE PIPE INSIDE 13-3/8" 13 21%-40% 41%-60% 61%-80% 81%-100 14 CL-4PP CL = 4CL-2 CL - 3 22-58 60+ 2-4 6-20 ODIP 15 50+ 6-12 14-26 28-48 IDIP 72-120 16 8-30 32-70 ODGC 18 - 36 38-68 70-112 114-IDGC 17 MAXIMUM FL RESPONSE IN VERTILOG UNITS 18 Vertilog interpretation chart provided with log for Figure 2. well P-32C.¹⁴ 19 Another problem with Vertilog is that there are multiple permutations associated with the 20 analysis of metal loss at any given depth, resulting in inherent uncertainty when interpreting the 21 22 results. For example, the Vertilog data relating to well FF-35B identifies some features as either 23 internal or external, and others as isolated pitting or general corrosion. Two relevant Vertilog 24 interpretation charts for FF-35B are shown here: (a) 86J55E, the chart shown in the upper portion 25 of Figure 2, and (b) 86P1E (Figure 3), which report different metal loss depths for the same 26 Vertilog signal. Depending on whether the metal loss at 6867 feet is classified as general 27 28 ¹⁴ Ex. II-4 (SCG00238148).

1	corrosion or isolated pitting, and depending on which interpretation chart is used, the reported							
2	dep	depth can nearly double. In other words, there are four permutations for a single depth data						
3	poii	point. The feature at 6867 feet is identified as either: (1) isolated pitting of 44% depth (86J55E),						
4	(2)	(2) isolated pitting of 37% depth (86P1E). (3) general corrosion of 32% depth (86J55E), or (4)						
5	σen	general corrosion of 25% denth (86P1E)						
6	501	eneral corrosion of 25% depth (80PTE).						
7								
8				VERTILOG INT	TERPRETATION	•		
9	4 1 8		C M	COMPANY: SOUTHER MELL: I.W. 82	RN CALIFORNIA	GAS COMPANY		
10	1 1 1		F C S	IELD: ALISO (NTY: LOS ANG TATE: CALIFOR	CANYON //// GELES RNIA			
12								
13							wall loss	
14		DEPTH	VERTILOG UNIT	LOCATION & EXTENT	CHART NO. 86J55E	CHART NO. 86P1E	PERCENT AVE	
15		74	20	ID or OD, IP	60 or 52	1	60 or 52	
16		2148		ID, IP OD, IP	34 39	r 1 1	34	
17		3962 4136		OD, IP OD or ID, IP OD, IP	30 or 19 30	1 1 1 1	30 or 19 30	
18		4841 6180	8	OD, IP OD, IP	30 31	24	30 27.5	
19		6682 6786 6825	34 10 12	OD, IP OD, IP OD, IP	60 33 36	53 26 29	29.5 32.5	
20		6867 6891	18 12	OD, IP or GC ID, IP	44 or 32 28	37 or 25	40.5 or 28.5 21.5	
21		6960 6971 6976	8 12 10	OD, IP OD, IP ID, GC	30 36 15	23 29 6	26.5 32.5 10.5	
22		7034	10 10 10	OD, IP OD, IP	33 33	26 26	29.5 29.5	
23		7078	76 64	ID, IP ID, IP ID, GC	94 86 ! 83+	87 75 72	90.5 80.5 77.5	
24		7123	16	OD or ID, IP ID, GC	42 or 36 42	35 or 20 25	38.5 or 28 33.5	
25			Figure 3	Vertilog interpretati	on. well FF-35R	11/11/1989 ¹⁵	1	
26			1 15010 5.	· •rms morprout				
27								
28	¹⁵ E	x. II-5 (SC	G00155502).	_				
				6				

1	Additional flaws of Vertilog were its inability to distinguish between defects and
2	hardware (such as centralizers and scratchers) and its difficulty interpreting corrosion located near
3	the surface casing shoe. Accordingly, alternate methods of presenting Vertilog data, described as
4	"Digital Vertilog" and consisting of reporting the signal from each flux leakage sensor, were
5 6	discussed in publications by Atlas Wireline Services in 1987 ¹⁶ and 1991. ¹⁷ These papers
7	concluded that transmitting the entire signal seen by the sensor coils better depicts the condition
8	of a casing in a well and provides more information regarding the physical parameters of the
9	"anomaly." The 1991 paper reported that log presentation of the type shown in Figure 1 above
10	was preferable for estimating the penetration of a defect; but regarding corrosion near the surface
11	casing shoe, the 1987 paper reported that what appears to be severe corrosion on the standard log
12	format is properly identified as minor corrosion when using the 12-channel log format.
13	Starting in approximately the early 2000s, Vertilog evolved into MicroVertilog
14	(MVRT). ¹⁸ The MVRT tool was equipped with ten each flux leakage and eddy current sensors,
15	similar to the Vertilog tool. MVRT output was more sophisticated than Vertilog and, in addition
17	to maximum hflux leakage and maximum eddy current, it included output from all of the flux
18	leakage and eddy current sensors, as well as "defect maps" displaying graphical representations
19	of flux leakage and eddy current data
20	
21	However, although MVRT presented data in a more sophisticated manner, it was found to
22	be essentially functionally equivalent to Vertilog, and MVRT had questionable accuracy and
23	reliability as well. As illustrated below, like Vertilog, MVRT consistently and significantly
24	overestimates pit depth (Table 2). ¹⁹
25	¹⁶ Ex. II-6 (Mato, S.A., "Multi-Channel Casing Inspection Instrument," 87-DT-102)
26	 ¹⁷ Ex. II-3 (SPE 22101). ¹⁸ Ex. II-7 (Al-Aimi, M.F., et al., "North Kuwait Down-hole Corrosion Management Challenge
27	and the Use of New Corrosion Detection Tools to Define the Extent of the Problem," SPE 81442, 2003).
28	¹⁹ Ex. II-8 (Newman, M.A., "The Importance in Developing a Surveillance Logging Quality Assurance and Quality Control Plan," SPE 84828, 2003).
	7

1									
2			MVRT Data			Ph	Physical Measurements		
3 4		Example	Model	Length (in)	Depth (%)	Length (in)	Width (in)	Depth (%)	
5		1	GC	1.7	100	1.75	3.00	69.1	
6		2	GC	0.7	83.5	1.0	1.5	53.8	
7		3	IP	1.4	42.9	1.5	1.5	18.0	
8		4	IP	1.4	44.1	2.00	3.00	24.5	
9	Table 2	Com	parison o	of MVRT	with Phy	sical Measu	irements of L	arge Diamete	er Pits
10		(GC	: general	corrosion	, IP: isola	ited pitting	, LDC: large	diameter corr	rosion)
11	C	$\frac{Due}{V}$	to Limitat	tions with	Vertilog,	Superior To	ols Such As H	ligh Resolution	<u>n</u>
12	F	<u>verti</u> IRVRT way	<u>llog (HK v</u> s develope	$\frac{(KI)}{M}$ and $\frac{(KI)}{M}$	of limitat	tions with V	<u>ertilog techno</u>	<u>e Developed.</u> logy As disci	ussed
13	first gene	eration MF	tools die	d not gene	rate verv	accurate or 1	eliable results	20 AS disci	usseu,
14	first generation MFL tools did not generate very accurate or reliable results. ²⁰								
15	I he Baker Hughes HRVRI used a greater number—and better quality—sensors, resulting								
16	in increased circumferential and axial resolution. The 1 ¹ / ₄ -in coil type sensors were replaced with								
17	¹ / ₄ -in Hall-effect sensors. ²¹ As further comparison, an HRVRT tool used 7-in to 9 ⁵ / ₈ -in diameter								
18	casing ar	nd containe	d 288 flux	k leakage s	sensors and	d 96 discrin	ninators (discri	iminators perfo	orm the
19	function	of the prev	iously use	ed eddy cu	rrent sens	ors). Vertil	og and MVRT	tools utilized	only 10
20	to 12 eac	h flux sens	ors and ec	ldy curren	t sensors.				
21	H	IRVRT rep	orts provi	de the ben	efit of ind	icating met	al loss feature	dimensions (le	ength,
22	width, and depth), identifying metal loss as internal or external, classifying features (pinholes,								
23	pits, gen	eral, axial g	grooving,	axial slotti	ng, circun	nferential g	rooving, and c	ircumferential	
24	slotting),	and calcul	ating safe	operating	pressure.	Classificat	ion of metal lo	oss features is l	oased on
25	width an	d length as	shown in	Figure 4.					
26 27	²⁰ See sup Technolo ²¹ Ex. II C	<i>ra</i> note 9, E gy is Better	x. II-2 (citi for You?,"	- ing Goedec Pipeline &	ke, H., GE z Gas Jourr	Oil & Gas"l nal, October 2	Ultrasonic or M 2003).	FL Inspection,	Which

 ²¹ Ex. II-9 (El Sherbeny, W., et al., "Magnetic Flux Leakage (MFL) Technology Provides the Industry's
 Most Precise Pipe Integrity Corrosion Evaluation, Accurately Characterizing Casing and Tubing Strength -Technology Overview and Case History," SPE 175871-MS, 2015).



SoCalGas-06.0011

1	imaging tools	yield excellent pipe thickness information with superior azimuthal resolution. Pipe				
2	thickness coupled with internal radii measurements make the reliability of this tool "fair" in					
3	determining in	ternal and external corrosion. ²⁵				
4	D.	<u>Follow-up Analyses by More Accurate Methods—USIT and HRVRT—</u> Confirmed that the Circa 1988 Vertilogs Returned False Positives and Were				
5		Therefore Not Reliable.				
6	Compa	arison of wells that were inspected by Vertilog circa 1988 and inspected				
7	subsequently b	by HRVRT and USIT demonstrates that Vertilog did not provide reliable data.				
8	1.	Of the five wells on the 1988 list with vendor-quantified Vertilog results, one well (SS-9) was subsequently logged almost 30 years later using both USIT and				
9		HRVRT. An additional well (FF-35B) not on the 1988 list was inspected using Vertilog in 1989 and also subsequently logged using both USIT and HRVRT.				
10 11		Review of logging results of these two wells shows that metal loss identified by Vertilog circa 1988 was not substantiated by subsequent logging, even after close to 30 years of additional service				
12	2	Vortilag inspection of the SS 0.7 in agains in December 1088 identified Class 2				
13	۷.	features in six casing joints between 2100 ft and 3800 ft (Figure 5). All of the features identified by Vertilog were indicated as isolated pitting, all were located				
14		immediately above casing collars, and all appeared similar even though three were identified as internal and three were identified as external. Multiple occurrences of similar signatures that were not identified as metal loss exist on the Vertilog chart				
15	2	USIT and HDVDT of the SS 0.7 in casing were performed in 2018 as part of				
16 17	5.	SoCalGas' comprehensive safety review and did not identify any of the metal loss features identified by Vertilog. USIT and HRVRT did not identify features greater				
18		from 2560 to 2570 ft that were reported as tool "eccentering." HRVRT did not identify any metal loss features greater than 18% wall thickness above 8522 ft. ²⁶				
19		Internal metal loss of 23% and 81% was identified by HRVRT at 8522 ft and 8543 ft, respectively.				
20	4.	Vertilog inspection of the FF-35B 8 ⁵ / ₈ -in casing in November 1989 identified multiple Class 2, 3, and 4 indications (Figure 7). The Class 3 and Class 4 Vertilog				
21		indications were not corroborated by the 2016 HRVRT and 2017 USIT logs, even though these logs were conducted 27 and 28 years after the Vertilog inspection				
22		(Figure 7). HRVRT did not identify external metal loss deeper than 21% of wall thickness and did not identify internal metal loss deeper than 26% of wall				
23		thickness. USIT did not identify metal loss greater than 19% of wall thickness, except for an area reported as 21.4% metal loss at 7020 ft depth.				
24	5.	In summary, the circa 1988 Vertilogs did not provide reliable casing metal loss $1 \pm \frac{27}{7}$				
25		data.				
20	²⁵ Ex. II-13 (Sin of Well Integrit	ngh, S.K., "An Integrated Approach to Well Integrity Evaluation via Reliability Assessment y Tools and Methods: Results from Dukhan Field, Qatar," SPE 156052, 2012).				
28	 ²⁰ HRVRT has a ²⁷ Figures 5 thro They do not inc 	a reporting threshold of 15% casing thickness loss. ough 9 display only anomalies that I have interpreted to be caused by potential wall loss. dude any anomalies that appear to reflect mechanical damage.				
		10				



SoCalGas-06.0013









1 2 3 4	SoCalGas has not demonstrated that it attempted to use the 1988 Vertilog results to assess the risk of well corrosion in its seven wells specifically or the Aliso Canyon wellfield more broadly. Had SoCalGas' management properly administered the program, the corrosion issues on SS-25 would have been timely identified. SoCalGas would then have been able to monitor or remediate or monitor the well and prevent the October 23, 2015 Leak ⁴⁰
ד ג	PAO's argument is incorrect, and PAO's entire premise is undermined by the fact that
6	calculating the corrosion rate requires much more than a "simple analysis." PAO's calculated
7	corrosion rates are speculative and unreliable, as PAO calculated its rates merely by dividing a
8	single casing thickness measurement by the maximum penetration from the Vertilog reports by
9	the length of time that the wells were in service. This method is insufficient as it does not
10	consider the many well-specific variables requiring analysis. External corrosion rates of an
10	underground structure depend on availability of water, the chemistry of the water, soil and/or
12	formation chemistry and resistivity, oxygen concentration, and the presence of certain microbes
12	Corrosion rates also often change over time due to changes in environmental conditions
13	Accordingly SoCalGas could not have simply used PAO's calculation method to identify
14	corrosion issues at Aliso Canyon generally, much less at SS-25. As Blade stated "There is no
13	way to know what an inspection of the SS-25 casing would have shown in 1088 "41
10	Nenotheless BAO and Plade estimate that SS 25 was already undergoing appreciable corresion
17	Nonemeters, PAO and Blade estimate that SS-25 was already undergoing appreciable conosion
18	at the time of the Vertilog testing. One of Blade's estimates provides that corrosion at SS-25
19	started in 1977, based on a linear corrosion rate of 7 mpy and the fact that corrosion reached 85%
20	maximum depth in the SS-25 7-in. casing in 2015. ⁴² Blade also estimated a linear corrosion rate
21	range of 5 to 10 mpy. ⁴³ Assuming a rate of 10 mpy, Blade's estimate provides that corrosion
22	could have started in 1988 and reached maximum measured depth of 85% in 2015. PAO
23	estimated corrosion rates of 1.4 to 4.6 mpy for wells on the 1988 list that were inspected using
24	
25	
26	⁴⁰ PAO Prepared Testimony at 9.
27	⁴¹ Blade Supplemental Report, "Review of the 1988 Candidate Wells for Casing Inspection," at 2 (emphasis added).
28	 ⁴² Blade Supplemental Report "SS-25 Casing Failure Analysis," p. 209. ⁴³ Blade Report at 123.
	16

Vertilog.⁴⁴ But even according to PAO's **authority**,⁴⁵ none of those purported corrosion rates warrant any action.

To the contrary, it is likely that external corrosion of the SS-25 7-in. production casing did not initiate until after the 1988 to 1990 time frame, in which case **there would have been no corrosion for a Vertilog to detect**. External corrosion of a production casing contained within a surface casing is unlikely to initiate until sufficient drilling fluid is displaced by water. The amount of time for this to occur is not known, and indeed, can take many years, if it happens at all.

9 Critically, the grooved, striated appearance of the SS-25 corrosion is consistent with
10 Microbiologically Influenced Corrosion (MIC).⁴⁶ This is important because corrosion associated
11 with MIC typically occurs at rates greater than Blade's estimated corrosion rate range of 5 to 10
12 mpy. Given the 85% corrosion depth reached in 2015, it is thus likely that any corrosion at SS-25
13 started many years after the circa 1988 Vertilog testing.

14 PAO and Blade appear to believe that methanogens caused the corrosion at SS-25, but

15 neither Blade nor PAO considered species more commonly associated MIC. Blade

16 acknowledged in its November 1, 2019 webinar that it did not perform sufficient testing to

17 adequately characterize bacteria present on the SS-25 surface casing.⁴⁷ In addition, microbial

18 communities are known to change substantially when environmental conditions change. No

19 testing for microbes was conducted on samples removed from the area of the rupture at the time

20 the ruptured casing was extracted from SS-25 in November 2017, and even by then the makeup of

21 the microbial community had likely changed completely since the rupture. Test results

22 identifying methanogenic microbes were taken from 7-in casing section 24 at a depth of 979 feet

- and 7-in casing section 25 at a depth of 1021 feet. These locations are 87 feet and 129 feet below
- 24

1

2

⁴⁵ PAO Prepared Testimony at 8 n. 39 ("In an open water system a corrosion rate of around 1 MPY is normal. Having corrosion rate of around 10, you should take action. Corrosion rates of 20 MPY and

⁴⁴ PAO Prepared Testimony at 8.

above, you should be concerned, as the corrosion is 'eating' the metal rather fast." Merus Oil and Gas, https://www.merusonline.com/mpy-milsper-year/).

^{27 &}lt;sup>46</sup> Éx. II-27 ("Microbiologically Influenced Corrosion (MIC): Methods of Detection in the Field," GRI Field Guide 1991, Gas Research Institute, Chicago, Illinois).

^{28 &}lt;sup>47</sup> Blade Root Cause Analysis Webinar, November 1, 2019 (recording available at https://www.youtube.com/watch?v=K67dIl6aapk&feature=youtu.be).

the rupture, respectively. The MIC samples were acquired in August 2018, as sections 24 and 25 were removed from the well, nine months after the ruptured casing section was removed from SS-25 and nearly three years after the rupture occurred. It is unreasonable to expect that microbes present in these samples were representative of microbes that existed in the area of the rupture at the time of the rupture.

Reports of corrosion caused by methanogens are rare, but sulfate reducing bacteria can
cause MIC and are frequently associated with corrosion of below-ground steel structures. The
typical pitting corrosion rates of 28 mpy for unprotected line pipe steel in the presence of sulfate
reducing bacteria are reported in the technical literature.⁴⁸ At 28 mpy, the SS-25 7-in. casing
would have corroded to the maximum measured depth of 85% in just under ten years (Figure
10)—meaning that no corrosion would have been present as late as 2005. Indeed, MIC pitting
rates greater than 250 mpy have even been reported in the technical literature.⁴⁹

27	⁴⁸ Ex. II-28 (Jack, Thomas R., "Biological Corrosion Failures," ASM Metal Handbook 10 th Edition,
	Volume 11, ASM International, 2002).

^{28 &}lt;sup>49</sup> Ex. II-29 (Larsen, K.R., "A Closer Look at Microbiologically Influenced Corrosion", Materials Performance, July 2015).



SoCalGas-06.0021

1 and interpretation of pressure testing results. Pressure testing is intended to detect existing casing 2 leaks, not wall loss. As established above in the discussion of USIT and Vertilog, there was no 3 critically sized damage in these wells. Put differently, pressure testing would not reveal a casing 4 leak absent severe pre-existing corrosion, and such testing will only confirm the absence of 5 critically sized damage. 6 To illustrate, we used the modified B31G method described by ASME B31G to calculate 7 safe operating pressure of corroded 7-in., 23 pound per foot J55 casing, which is the type of 8 casing that was used in the upper portions of the aforementioned seven Vertilog-tested wells at 9 Aliso Canyon (Figure 11).52 10 Our calculations show, for example, that safe operating pressure of a casing with local 11 metal loss of up to 50% wall thickness (Vertilog mid-range Class 3) and 10-in length, is greater 12 than the 115% MAOP (3625 psi) mechanical integrity test pressure required by current California 13 regulations (Figure 11). 14 Our calculations further show that safe operating pressure for casing with metal loss up to 15 60% wall thickness (boundary between Vertilog Classes 3 and 4) and 10-in length is above the 16 approximately 3150 psi casing MAOP. 17 As shown below, pressure testing only reveals critical defects.⁵³ Of the wells listed in the 18 1988 memo that were pressure tested, pressure testing was performed no higher than 115% 19 MAOP. Therefore, PAO's allegation that pressure testing would have revealed integrity issues 20 for SS-25 is pure speculation. 21 22 23 24 25 26 ⁵² Ex. II-31 (Manual for Determining the Remaining Strength of Corroded Pipelines, ASME B31G-2012). 27 ⁵³ PAO states that "There is no minimum amount of corrosion or metal loss that should necessitate remediation; instead, once the wellbore is proven to be found in a corrosive environment, such a finding 28 would "necessitate immediate remediation." Ex. II-30 (PAO Response to SoCalGas First Set of Data Requests, response to Question 3). PAO's response could not be further from reality.



protection to the 11 3/4-inch casing.").

1	This is not so. Cathodic protection (CP) does not protect production casing where it is
2	contained within surface casing. CP will protect only the outermost casing of a multiple casing
3	string, and therefore could not have protected the SS-25 7-in. casing at the rupture location. In a
4	well where multiple casing strings are used, external cathodic protection will only protect that
5	portion of each casing string in contact with the formation. ⁵⁷ The SS-25 7-in. casing failure
6	occurred at a depth of 892 ft, a location where the 7-in. casing is contained within the 990 ft. deep
7	11 ³ / ₄ -in surface casing. Cathodic protection would not have protected the 7-in. casing above 990
8	ft. In fact, PAO acknowledged, as did Blade, that CP would not have protected the 7-in. casing
9	inside the 11 ³ / ₄ -in casing. ⁵⁸
10	In addition, CP of the surface casing was not necessary. There is no conclusive evidence
11	that there were holes in the 11 ³ / ₄ -in surface casing prior to rupture of the production casing. And,
12	even if that were the case, Blade found that water entered the B-annulus through the casing
13	shoe. ⁵⁹ In any event, Blade also concluded that the holes in the 11 ³ / ₄ -in surface casing were
14	likely a "consequence of"-not a cause of -the axial rupture of the production casing:
15	The holes may have been a consequence of an internal pressure of
16	surged to 800 psi at one point right after the axial rupture. The
17	noies are likely a consequence of the axial rupture. ⁵⁰
18	The gas flowing through the axial rupture on the 7 in. production casing caused an increase in pressure on the 11 3/4 in. surface
19	to fail, creating holes and thus providing a pathway for gas to
20	escape. Over 50 such holes provided a pathway for the gas to surface. ⁶¹
21	Although Blade stated, "Some of these approximately 58 holes [in the 11 ³ / ₄ -in surface
22	casing] could have existed prior to the 7 in. casing axial rupture," in the next sentence in its RCA
23	Report, Blade states: "Many of the holes exhibited sharp corners that may have been more typical
24	⁵⁷ Ex. II-32 (J.H. Morgan, Cathodic Protection, Second Edition, NACE International, 1987, p. 222)
25	⁵⁸ Ex. II-30 (PAO Responses to SoCalGas First Set of Data Requests, response to Question 14 ("While a cathodic protection system would have provided corrosion protection to the 11 3/4 in casing it would not
26	have protected the 7 in. casing inside the 11 3/4 in. casing.") (quoting Blade May 16, 2019 Report, p. 215)).
27	⁵⁹ Blade Report at 100. ⁶⁰ Blade Report at 119 (emphasis added).
28	⁶¹ Blade Report at 3.
	22

1	of a burst failure, implying that they occurred due to a pressure surge in the surface casing." ⁶²
2	PAO further ignores that CP can be ineffective and even harmful to neighboring wells.
3	CP might be ineffective if MIC is simultaneously occurring because MIC can increase the
4	kinetics of corrosion reactions, increasing the required CP current, and in turn increasing the risk
5	of undesirable results such as stray currents. ⁶³ MIC in some cases cannot be stopped by CP, even
6	when using very large negative potentials. ⁶⁴ Moreover, CP installation at SS-25 could have been
7	detrimental to wells SS-25A and SS-25B.65 For example, stray electrical currents from CP can
8	cause accelerated corrosion. ^{66, 67}
9 10	V. SED IS INCORRECT THAT CONTINUOUS PRESSURE MONITORING AND TEMPERATURE/NOISE SURVEYS SHOULD HAVE ALERTED SOCALGAS TO THE SS-25 LEAK PRIOR TO OCTOBER 23, 2015.
11	A. <u>Continuous Pressure Monitoring Would Not Have Allowed SoCalGas to Detect</u> <u>the Leak Before It Occurred.</u>
12	SED alleges that the lack of continuous pressure monitoring prevented immediate
13	identification of the SS-25 leak and accurate estimation of the gas flow rate. ⁶⁸ Unlike the Blade
14	report, ⁶⁹ SED did not go so far as to state that real-time pressure monitoring could have prevented
15	the brittle circumferential parting from occurring. However, SED's sole sponsoring witness
10	Margaret Felts testified that continuous, real-time pressure monitoring would have enabled
17	SoCalGas to shut in the SS-25 well and avoid "catastrophic failure" of the 7-in. casing. ⁷⁰
10	This is wrong. It was not possible to detect a leak and take action prior to the parting of
20	the 7-in. casing because the 7-in. casing was not leaking prior to October 23, 2015. The rupture
20	and parting of the SS-25 7-in. casing occurred in a single, rapid event.
21 22	
22	⁶² Blade Report at 119 (emphasis added). ⁶³ Fx JL-33 (NACE TM0106-2016 "Detection Testing and Evaluation of Microbiologically Influenced
23 24	Corrosion (MIC) on External Surfaces of Buried Pipelines."). ⁶⁴ Fx II-34 (Deltares S L et al. "Cathodic Protection and MIC – Effects of Local Electrochemistry."
25	NACE Corrosion 2017, Paper No. 9452). ⁶⁵ See SoCalGas Reply Testimony Chapter I (Hower/Stinson) at Section 3 F
26	⁶⁶ Ex. II-35 (Holtsbaum, Brian W., "Well Casing External Corrosion and Cathodic Protection," ASM Handbook, Volume 13C: Corrosion, ASM International, 2006, p. 97)
27	⁶⁷ Ex. II-36 (NACE-SP0186 discussion of electrical isolation); Ex. II-37 (API-59-199 page 212 for more on stray currents.
28	 ⁶⁸ SED Opening Testimony at 47. ⁶⁹ Blade Report at 230.
20	⁷⁰ Ex. I-10 (Felts Depo. Tr. 270:17).
	23

1	The Blade main report and various supplemental reports assert that the SS-25 7-in.
2	casing's vertical rupture and circumferential parting were two separate events, with the
3	circumferential parting occurring some period of time after the initial vertical rupture, but while
4	the well was still on injection. To the contrary, it is evident the SS-25 7-in. casing vertical rupture
5	and circumferential parting occurred as a single event, as illustrated in Figure 12 and Figure 13,
6	and for the reasons described below:
7 8	• The SS-25 fracture surface exhibits clear chevron marks at a number of locations. Chevron marks denote the direction of propagation of cracks in steels – the apex of the chevron points toward the fracture origin (Figure 14). Chevron marks on the
9	SS-25 fracture surface show clearly that the circumferential fracture is an
10 11	remarkably similar chevron marks shown in a textbook on failure analysis (Figure 16). ⁷¹
12	• Blade's contention that a separate fracture origin exists on the circumferential
13	portion of the fracture is incorrect (Figure 17). Rather than a fracture origin, this area is merely a continuation of the circumferential portion of the fracture.
14	Fracture surface markings within the hypothesized origin are the same as or similar to those outside of the origin.
15 16	• The Blade report says nothing about how this alleged fracture origin came into existence. If the origin was created during the casing manufacturing process or by a sub-critical crack growth mechanism such as fatigue or stress-corrosion, the
17	surface of the origin would appear distinctly different.
18 19	• Blade's inability to determine the size of alleged fracture origin (they report it as 5.22 mm deep and either 14.54 mm long or 21.72 mm long ⁷²) is consistent with the absence of features identifying it as an origin.
20	• Blade's scanning electron microscope (SEM) photos of the hypothesized origin
21	show predominantly cleavage features. ⁷³ Blade reported that no noticeable changes in fracture mode were observed outside of the origin ⁷⁴ and their SEM
22	photographs corroborate this. As such, the hypothesized origin must have been created by mechanical force in the same manner as the circumferential parting.
23	• Blade's analysis of the circumferential parting is logically flawed. According to
24	Blade's analysis of the encenterential parting is regionly framed. Theorem is the Blade's analysis and calculations, the origin was required for circumferential parting to accur as a separate event. But the fracture mode of the origin is the
25 26	same as that of the circumferential parting, begging the question as to how the
20 27	⁷¹ Ex. II-38 (Wulpi, Donald J., Understanding How Components Fail, American Society for Metals, 1985,
28	 ⁷² Blade Supplemental Report, SS-25 Casing Failure Analysis, at 166. ⁷³ Blade Supplemental Report, SS-25 Casing Failure Analysis, at 140-142. ⁷⁴ Blade Supplemental Report, SS-25 Casing Failure Analysis, at 143.
	24



SoCalGas-06.0027







1	localized cooling; indeed, cooling behavior where a storage well meets the reservoir has been well known for many years, as can be seen in Figure 19. ⁸⁰
2 3 4	• All storage wells at Aliso Canyon exhibit the same or similar cooling at that depth. For example, Figure 20 shows that Fernando Fee 32A and Porter 72A both exhibit cooling at the bottom of the wells, and the same is true for SS-25A and SS-25B (Figure 21).
5 6 7 8 9	• Some temperature surveys over the years reported possible slight leakage in the vicinity of the production casing shoe and noise logs were run following a number of these temperature surveys. SoCalGas performed noise logs in SS-25 on the following ten dates: September 8, 1978, December 11, 1978, August 8, 1979, November 24, 1981, February 23, 1983, April 11, 1984, July 27, 1984, November 7, 1991, November 7, 2006, and June 1, 2012. None of these noise logs indicate a gas leak in the production casing. None of these noise logs indicate a gas leak in the production casing or at the production casing shoe.
10 11 12	• A radioactive tracer survey performed on July 29, 1984 reported possible slight leakage behind pipe from top perf at 8510 ft up to around 8430 ft and 8190 ft. This survey indicates gas flowing up to the bottom of the cap rock at approximately 8182 ft and into the permeable S1 formation.
13 14 15 16 17	• The noise logs display four curves, representing sound at frequencies of 200 Hz, 600 Hz, 1,000 Hz, and 2,000 Hz, respectively. Low frequency noise (200 and 600 Hz) is usually indicative of surface noise or low rate flow of fluids behind casing. High frequency noise (1,000 and 2,000 Hz) is usually indicative of the flow of gas, bubbling of gas in liquids, or high-rate gas flow. The interpretation of noise logs is well-established: a sharply-defined, high-frequency noise over a short length of casing is an indication of a gas leak. ^{81 82 83}
 18 19 20 21 	• There are no such sharply-defined, high-frequency noises over short lengths of casing in the SS-25 noise logs that would indicate the presence of a gas leak. In some of the logs, there is a noticeable sharp peak in noise, but these were caused by the operators testing the noise logging tool prior to entering the completion equipment at or below 8,000 ft., and these operator tests are clearly labeled on the logs (see, e.g., November 24, 1981 log).
22 23	• SoCalGas performed the noise log of December 11, 1978 from 5,800 to 7,770 ft., and that log measured no anomalous noise. The logs of November 7, 2006 and
 24 25 26 27 28 	 Ex. II-39 (Bird, J. M. (1954, January 1). Interpretation of Temperature Logs in Water- and Gas-injection Vells and Gas-producing wells. American Petroleum Institute). Ex. II-40 (Smith, B. A., & Neal, M. R. (1970, January). Evaluation of Gas Storage Well Completions with Well Logs. Society of Petroleum Engineers. doi:10.2118/2965-MS). Ex. II-41 (McKinley, R. M. (1994, July). Temperature, Radioactive Tracer, and Noise Logging for njection Well Integrity. Report No. EPA/600/R-94/I24 for Cooperative Agreement No. CR-818926. Ex. II-42 (McKinley, R. M., & Bower, F. M. (1979, November 1). Specialized Applications of Noise ogging). Society of Petroleum Engineers. doi:10.2118/6784-PA).
	29

1	June 1, 2012 were performed for the entire length of the well and measured no anomalous noise.
2	• SoCalGas performed the remaining noise logs performed in 1978, 1979, 1981.
3	1984 (2 runs), and 1991 to assess potential leaks. All logs measured generally shallow low frequency noise (200 to 600 Hz). These low-frequency measurements
5	are interpreted to originate from surface noise at the Aliso Canyon site or operations in nearby wells, which is common and described by McKinley [1995]. ⁸⁴
6	The 1978 log includes operator comments referencing surface noise.
7	• The same six logs also measured noise across all four frequency ranges slightly above the packer and completion equipment at the base of the well, and across the storage formation. Such noise is expected and is associated with movement of gas
0	in the storage formation and through the completion equipment. The 1991 log
10	about 7,500 ft., which is shown in the excerpt of the log in Figure 22. As can be
11	7,600 ft. and the indicated bubbling noise was not detected.
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
23	
24	
25	
26	
27	
28	sources of noise, especially that due to surface machinery, on the quality of a noise survey. The failure to recognize such sources is characteristic of an inexperienced logging engineer.").
	30









SoCalGas-06.0036

1	WITNESS QUALIFICATIONS
2	My name is Robert A. Carnahan. My business address is Exponent, Inc. 5401 McConnell
3	Avenue, Los Angeles, California 90066.
4	Credentials and Qualifications
5	1. I am a Principal Engineer at Exponent, Inc. ("Exponent"). I hold an M.S. degree
6	in Metallurgical Engineering from the University of Michigan. I hold a B.S. degree in Materials
7	and Metallurgical Engineering, also from the University of Michigan. I am a licensed
8	Professional Mechanical Engineer in the states of Arizona, California, Michigan, Nevada, Texas,
9	and Utah. My qualifications are described in greater detail below and summarized in my
10	curriculum vitae, attached as Exhibit 1.
11	2. I am certified by the American Petroleum Institute (API) as a corrosion and
13	materials professional (API 571).
14	3. I have expertise in physical metallurgy, materials selection, failure analysis and
15	prevention, fracture mechanics, corrosion, including microbiological influenced corrosion,
16	welding, engineering mechanics, and machine design.
17	4. From 1980 through 1986, I was employed in the Nuclear Energy Division of
18	General Electric Company in San Jose, California. While at General Electric Company, I
20	performed research on stress corrosion cracking of stainless steels and nickel base alloys. I
21	installed an in-situ stress corrosion cracking test at an operating nuclear power plant, which
22	utilized the DC potential drop method to monitor crack growth. I visited numerous nuclear power
23	plants in the United States and abroad to investigate cracks in stainless steel piping and other
24	types of failures. I performed laboratory failure analysis of a variety of components from
25	operating nuclear power plants. During my career at General Electric, I developed special
26	expertise in many areas of metallurgical engineering and corrosion, which are areas at issue in
21 28	this arbitration.
	25
	55

1	5. While at General Electric, I was admitted to the Materials Science and Engineering
2	department at Stanford University and took the core courses required for a Ph.D.
3	6 From 1987 through most of 1988 I was employed in the Aerospace Division of
4	General Electric and worked on a space pueleer power project known as SP 100. For the SP 100
5	General Electric and worked on a space indefeat power project known as 51-100. For the 51-100
6	project, I investigated creep-rupture behavior of niobium alloy fuel cladding, compatibility of
7	niobium structural alloys with liquid lithium, neutron irradiation resistance of carbon-carbon
8	composites, and bearing materials for use in an aggressive elevated temperature, high vacuum,
9	high neutron flux environment.
10	7. In 1988, I was hired by Failure Analysis Associates, Inc. (now Exponent) in Palo
11	Alto, California (and now Los Angeles), where I have developed a consulting practice in the areas
12	of metallurgical, corrosion, and mechanical engineering. With specific focus on oil and gas
13	industry projects, I have performed failure analysis of a variety components, including pipelines,
14	heat exchangers in hydrogen service, cryogenic brazed aluminum plate-fin heat exchangers,
16	piping in HF alkylation units, and pumps in flammable service.
17	P I have not maximusly testified before the Commission
18	8. I have not previously testified before the Commission.
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
-	
	36